

# Types of stresses

**Mr. RAJNITU R R**  
Assistant Professor  
Mechanical Department

# Factor of Safety

Structural members or machines must be designed such that the working stresses are less than the ultimate strength of the material.

$FS$  = Factor of safety



$$FS = \frac{\sigma_u}{\sigma_{all}} = \frac{\text{ultimate stress}}{\text{allowable stress}}$$

Factor of safety considerations:

- uncertainty in material properties
- uncertainty of loadings
- uncertainty of analyses
- number of loading cycles
- types of failure
- maintenance requirements and deterioration effects
- importance of member to structures integrity
- risk to life and property
- influence on machine function



# Shearing Stress Examples

Single Shear




$$\tau_{\text{ave}} = \frac{P}{A} = \frac{F}{A}$$

Double Shear



$$\tau_{\text{ave}} = \frac{P}{A} = \frac{F}{2A}$$


# Bearing Stress in Connections



- Bolts, rivets, and pins create stresses on the points of contact or *bearing surfaces* of the members they connect.
- The resultant of the force distribution on the surface is equal and opposite to the force exerted on the pin.
- Corresponding average force intensity is called the bearing stress,

$$\sigma_b = \frac{P}{A} = \frac{P}{td}$$


# Stress in Two Force Members




- Axial forces on a two force member result in only normal stresses on a plane cut perpendicular to the member axis.
- Transverse forces on bolts and pins result in only shear stresses on the plane perpendicular to bolt or pin axis.
- Will show that either axial or transverse forces may produce both normal and shear stresses with respect to a plane other than one cut perpendicular to the member axis.

# Stress on an Oblique Plane

- Pass a section through the member forming an angle  $\theta$  with the normal plane.



- From equilibrium conditions, the distributed forces (stresses) on the plane must be equivalent to the force  $P$ .





- Resolve  $P$  into components normal and tangential to the oblique section,

$$F = P \cos \theta \quad V = P \sin \theta$$

- The average normal and shear stresses on the oblique plane are

$$\sigma = \frac{F}{A_\theta} = \frac{P \cos \theta}{A_0 / \cos \theta} = \frac{P}{A_0} \cos^2 \theta$$


$$\tau = \frac{V}{A_\theta} = \frac{P \sin \theta}{A_0 / \cos \theta} = \frac{P}{A_0} \sin \theta \cos \theta$$




# Maximum Stresses




(a) Axial loading



(b) Stresses for  $\theta = 0$



(c) Stresses for  $\theta = 45^\circ$



(d) Stresses for  $\theta = -45^\circ$

- Normal and shearing stresses on an oblique plane

$$\sigma = \frac{P}{A_0} \cos^2 \theta \quad \tau = \frac{P}{A_0} \sin \theta \cos \theta$$


- The maximum normal stress occurs when the reference plane is perpendicular to the member axis,

$$\sigma_m = \frac{P}{A_0} \quad \tau' = 0$$

- The maximum shear stress occurs for a plane at  $\pm 45^\circ$  with respect to the axis,

$$\tau_m = \frac{P}{A_0} \sin 45 \cos 45 = \frac{P}{2A_0} = \sigma'$$

# Stress Under General Loadings





- A member subjected to a general combination of loads is cut into two segments by a plane passing through Q

- The distribution of internal stress components may be defined as,

$$\sigma_x = \lim_{\Delta A \rightarrow 0} \frac{\Delta F^x}{\Delta A}$$



$$\tau_{xy} = \lim_{\Delta A \rightarrow 0} \frac{\Delta V_y^x}{\Delta A} \quad \tau_{xz} = \lim_{\Delta A \rightarrow 0} \frac{\Delta V_z^x}{\Delta A}$$



- For equilibrium, an equal and opposite internal force and stress distribution must be exerted on the other segment of the member.



# State of Stress



- Stress components are defined for the planes cut parallel to the  $x$ ,  $y$  and  $z$  axes. For equilibrium, equal and opposite stresses are exerted on the hidden planes.

- The combination of forces generated by the stresses must satisfy the conditions for equilibrium:

$$\sum F_x = \sum F_y = \sum F_z = 0$$

$$\sum M_x = \sum M_y = \sum M_z = 0$$

- Consider the moments about the  $z$  axis:

$$\sum M_z = 0 = (\tau_{xy}\Delta A)a - (\tau_{yx}\Delta A)a$$

$$\tau_{xy} = \tau_{yx}$$

$$\text{similarly, } \tau_{yz} = \tau_{zy} \quad \text{and} \quad \tau_{xz} = \tau_{zx}$$

- It follows that only 6 components of stress are required to define the complete state of stress

Thank you